
Ferrite (magnet)

From Wikipedia, the free encyclopedia

Ferrites are electrically non-conductive ferrimagnetic ceramic compound materials, consisting of various mixtures of iron oxides such as Hematite (Fe_2O_3) or Magnetite (Fe_3O_4) and the oxides of other metals.



BEST AVAILABLE COPY